

DP-305003

Spiral Technologies, Inc., Troy, MI

Replacement  
Sheet

1/2




FIG. 1 FIG. 2 FIG. 3 FIG. 4 FIG. 5 FIG. 6 FIG. 7




FIG. 8 FIG. 9

BEST AVAILABLE COPY

DP-305003

Dolton Technical, Inc., Troy, MI

2/2


Replacement  
Sheet

FIG. 10